




SECTION ON A - A ISOMETRIC


Cutting plane A - A passes at right angles through the rib / web therefore it is cross hatched.




Cutting plane B - B passes longitudinally through the axis of rib / web therefore it is NOT cross hatched.



SECTION ON A - A




SECTION ON B - B



RIGHT VIEW

SECTIONING OF CASTINGS



SECTION ON B - B ISOMETRIC

